

## CORIOdiscover (v1.8.3.5)

Released by: Neil Baptiste

12/Jul/2023

This software is for:

- Hardware: CORIOmaster2 (CM2-541), CORIOmaster2 (CM2-547), CORIOmaster™ (C3-540), CORIOmaster mini™(C3-510), CORIOmaster micro™ (C3-503), CORIOmatrix™ (C3-340), CORIOmatrix™ MX (C3-440), CORIOmatrix™ mini (C3-310), and CORIOview™.
  - Firmware [CORIOmaster]: M412 or later (CORIOmaster, CORIOmaster mini, CORIOmaster micro),
  - Firmware [CORIOmatrix]: M412 or later (CORIOmatrix, CORIOmatrix MX and CORIOmatrix mini)
  - Firmware [CORIOview]: M405 or later
  - Firmware [CORIOmaster2]: G503 or later but not including V600 and above.
  - Operating systems: Microsoft® Windows® 7 and above
- ✔ You can run multiple instances of CORIOdiscover on the same PC.
- ✔ For help with using CORIOdiscover, see <http://tvone.com/tech-support/software/185-coriodiscover-software-download>

### Downloads

Download the latest firmware here: [tvone.com/firmware-updates](http://tvone.com/firmware-updates)

Download the latest software here:

CORIOgrapher:

<http://tvone.com/tech-support/software/183-coriographer-software>

CORIOdiscover:

<http://tvone.com/tech-support/software/185-coriodiscover-software-download>

You might need to manually install Microsoft .NET framework 4.8.1 Download it here: <https://dotnet.microsoft.com/en-us/download/dotnet-framework/thank-you/net481-web-installer>

- ❗ Save installers to your local PC.  
Don't install software from installers saved to network drives.

### Previous releases

Read details on previous releases here:

<http://tvone.com/tech-support/software/185-coriodiscover-software-download>

## CORIOdiscover (v1.8.3.5)

Released by: Neil Baptiste

12/Jul/2023

### New

- Added Support for CM2-541 product (variant letter and model name)
  - Support the W variant for CM2-541
- Increased the maximum wait time for the device to boot after the last reboot to 330 seconds (5.5 minutes)
  - This will now go to Done with Errors state if the reboot times out
- This CORIOdiscover does not support MK2 devices (CM2-547-mk2 which use FW V600 and above).

### Fixed

- CD shows "Device has not rebooted" error dialog box after CM2 update completes.
  - Increase the wait for reboot maximum timeout to 17.5 minutes as a loaded device set to DHCP with no DHCP server was taking longer than 5.5 minutes.
- Increased the TFTP retry to 15 seconds (15x 1 second retry). This should help with slow/unreliable networks.

### Notes

- This CORIOdiscover does not support MK2 devices (CM2-547-mk2 or CM2-547 devices that have been upgraded with the new CPU module). These use FW V600 and above).

### Contact us

[www.tvone.com](http://www.tvone.com)

tvONE NCSA  
North, Central and South America

✉ Sales: [sales@tvone.com](mailto:sales@tvone.com)  
Support: [tech.usa@tvone.com](mailto:tech.usa@tvone.com)

tvONE EMEA  
Europe, Middle East, Africa and Asia Pacific

✉ Sales: [sales.europe@tvone.com](mailto:sales.europe@tvone.com)  
Support: [tech.europe@tvone.com](mailto:tech.europe@tvone.com)