

CORIOmaster™ firmware M406BS1

This software is for:

- Hardware: CORIOmaster™ (C3-540).
 - Firmware: M307 or later, use CORIOdiscover™ V1.6.2.1 or later to update to this version
 - Control Software: CORIOgrapher™ v2.7.2.5 or later
- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest control software here:

CORIOgrapher: tvone.crmdesk.com/answer.aspx?aid=20766

CORIOdiscover (firmware updating tool): tvone.crmdesk.com/answer.aspx?aid=21697

Previous releases

Read details on previous releases here:

tvone.crmdesk.com/image.aspx?mode=file&id=14806

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

January 2019 CORIOmaster firmware M406BS1

Released 4-10-19 By: Neil Baptiste

New Features

- None

Fixed

- Intermittent DMA (Direct Memory Access) failures after update or reboot of the unit. Unit fails to boot and appears dead. Module status LED's are RED.

Known Issues

The REST API command;
<http://{{serverIP}}/api/{{ApiVersion}}/system/comms/ethernet/restartethernet> will crash the unit if the CPU does not have the new Real Time Clock module fitted.
Workaround = power cycle.