

CORIOmaster™ firmware M406BS5

This software is for:

- Hardware: CORIOmaster™ (C3-540).
 - Firmware: M307 or later, use CORIOdiscover™ V1.6.2.1 or later to update to this version
 - Control Software: CORIOgrapher™ v2.7.2.5 or later
- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest control software here:

CORIOgrapher: tvone.crmdesk.com/answer.aspx?aid=20766

CORIOdiscover (firmware updating tool): tvone.crmdesk.com/answer.aspx?aid=21697

Previous releases

Read details on previous releases here:

tvone.crmdesk.com/image.aspx?mode=file&id=14806

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

March 2020 CORIOmaster firmware M406BS5

Released 31-03-20 By: Neil Baptiste

New Features

- None

Fixed

- - ISCURRENT_CHANGED Event only raised when the storyboard is activated and not when deactivated.
- Corruption can be seen when changing Window quality with a DVI-I output module with a V2 scaler module fitted.

Known Issues

The REST API command;
<http://{{serverIP}}/api/{{ApiVersion}}/system/comms/ethernet/restartethernet> will crash the unit if the CPU does not have the new Real Time Clock module fitted.
Workaround = power cycle.