

CORIOgrapher (v3.2.3.1)

Released by: Neil Baptiste

04-May-21

This software is for:

- Hardware: CORIOmaster2™ (CM2-547), CORIOmaster™ (C3-540), CORIOmaster™ mini (C3-510), CORIOmaster™ micro (C3-503), and CORIOview.
 - Firmware [CORIOmaster2] : M502 or later
 - Firmware [CORIOmaster] : M410 or later
 - Firmware [CORIOview] : M409 or later
 - use CORIODiscover V1.7.2.3 or later to update to this firmware.
 - Software: CORIOgrapher v3.2.3.1
- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest control software here:

CORIOgrapher: <https://tvone.com/tech-support/software>

CORIODiscover: <https://tvone.com/tech-support/software>

Previous releases

Read details on previous releases here:

<https://tvone.com/tech-support/software>

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com


CORIOgrapher (v3.2.3.1)

Released by: Neil Baptiste

04-May-21

[New Features CORIOmaster variants with FW M410 and above and CM2 M501 or above only]

- Support for the new 4x4K input module (**CM2 547 only**)
- New Resolution Editor for outputs
 - Add or edit user definable custom resolutions from within CORIOgrapher.



* Please read the manual for the full instructions on using the new **Resolution Editor** for outputs *

- 700W PSU support
- HDCP support changes
- Pending/Take button changes
- Added Layout only presets
- HDMI 8out card channel pairing changes
- Highlighting items in the list also highlights in the editor and preview
- Consolidated build for all CORIOgrapher supported products

Fixed

- Editor still window preview does not scale to fit window.
- Offline CORIOmaster2 config detected as incompatible when loaded to a connected device.
- Dedicated windows missing after loading a config.

Notes

Known Issues:

- If you are installing CORIOgrapher v3.2 and already have CORIOgrapher v2.9 installed, then double clicking a CMC config file may still open in v2.9. If the CMC files do not automatically register to v3.2 you can change this by right clicking the file, selecting Open with..., and then choosing CORIOgrapher v3.2 from the list.
- Encoder Manager dialog uses tabs and the tab default behavior changes the selected tab highlight when the mouse hovers over child items.
- Application Window title bar is not themed.
- Changing pixel clock on an active custom resolution has no effect.
- Canvas Cut-to-black will overwrite the current output cut-to-black and canvas audio mute values, which means the previous values cannot be restored.