

CORIOview firmware M405P66B

This firmware is for:

- Hardware: CORIOview
- Software: CORIOgrapher v2.7.2.5

Use CORIODiscover V1.6.2.1 to update to this version

- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest software here:

CORIOgrapher: tvone.crmdesk.com/answer.aspx?aid=20766

CORIODiscover: tvone.crmdesk.com/answer.aspx?aid=21697

Previous releases

Read details on previous releases here:

<http://tvone.crmdesk.com/answer.aspx?aid=27753>

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

March 2019 CORIOview firmware M405P66

Released by: Bruce Meldrum

New

- none

Fixed

- Incompatibility with CORIOgrapher v2.7.2.5 and CM-AVIP modules which meant Items could not be added to the play queue.

Notes

- No other changes compared to firmware M405_66