

## CORIOgrapher (v2.6.3.2)

This software is for:

- Hardware: CORIOview™ [New], CORIOmaster™, CORIOmaster mini™, CORIOmaster micro™,
- Firmware: M405\_66B
- Software: Use CORIODiscover v1.5.2.2 or above to update to this version.

- ✓ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

### Downloads

Download the latest firmware here: [tvone.com/firmware-updates](http://tvone.com/firmware-updates)

Download the latest software here:

CORIOgrapher: [tvone.crmdesk.com/answer.aspx?aid=20766](http://tvone.crmdesk.com/answer.aspx?aid=20766)

CORIODiscover: [tvone.crmdesk.com/answer.aspx?aid=21697](http://tvone.crmdesk.com/answer.aspx?aid=21697)

### Previous releases

Read details on previous releases here:

[tvone.crmdesk.com/image.aspx?mode=file&id=14137](http://tvone.crmdesk.com/image.aspx?mode=file&id=14137)

### Contact us

[www.tvone.com](http://www.tvone.com)

tvONE NCSA  
North, Central and South America

✉ Sales: [sales@tvone.com](mailto:sales@tvone.com)  
Support: [tech.usa@tvone.com](mailto:tech.usa@tvone.com)

tvONE EMEA  
Europe, Middle East, Africa and Asia Pacific

✉ Sales: [sales.europe@tvone.com](mailto:sales.europe@tvone.com)  
Support: [tech.europe@tvone.com](mailto:tech.europe@tvone.com)

## CORIOgrapher (v2.6.3.2)

Released by: Neil Baptiste

### New

- None

### Fixed

- CORIOgrapher Save button on [Wall Editor] Add Display window greyed out, inactive.
- Changing ethernet setting from Static to DHCP on CORIOgrapher did not apply.

### Notes

- None